



Vehicle Diagnostic Report




Shop Name: Commercial Auto Glass East Rand	Tel: 0118224767
Email: zama@commercialautoglass.co.za	Web: www.commercialautoglass.co.za
Shop Number: 5	Address: Greenhills centre CNR Northreef rd & AG De Witt Dr. Bedfordview, Bedfordview, 2008, Johannesburg
Technician: frank	Scanner: Autel MaxiSys
Serial number: VB8GK1C01094	Version number: V5.73-6.10

Scan type	Pre-scan&Post-scan	Repair order	JS62KBGP
Customer information			
Title	18MY Subaru Asia & Pacific/Impreza / XV		
Year	18MY	VIN:	JF1GT7KL5JG034415
Make	Subaru	Lic Plate	js62kbgp
Model	Asia & Pacific/Impreza / XV	Odometer Mileage	37346
Sub model	18MY	Color	
Engine			




Pre-scan Report		2020-11-12 15:04:39
System	Calibration	Status
BCM (Body control)		Pass No Fault
RKE (Keyless access with push button start)		Pass No Fault
MFD (Multi-function display)		Pass No Fault
INF (Infotainment)		Pass No Fault
PWD (Power window (driver))		Pass No Fault
PWP (Power window (passenger))		Pass No Fault
PWS (Power window (switch))		Pass No Fault

Technician notes



Post-scan Report



2020-11-12 16:48:31

System	Calibrated	Status
LT (Headlight / Foglight)		Pass No Fault 
RH (Subaru rear vehicle detection)		Pass No Fault 
LH (Subaru rear vehicle detection)		Pass No Fault 
INF (Infotainment)		Pass No Fault
PWD (Power window (driver))		Pass No Fault
PWP (Power window (passenger))		Pass No Fault
PWS (Power window (switch))		Pass No Fault
RAB (Reverse automatic braking)		Fault 1

DTC


System	Codes	Description	Status
RAB (Reverse automatic braking)	B2C22	Eyesight system	Current

ADAS

Lane camera calibration	Static calibration	2020-11-12 16:36:07
* Repaired stereo camera		
* Replaced front windshield		



Technician notes



Customer's name: _____

Technician: _____

Date: _____

Notice: Please save a copy of this report for your records.